

Municipal Infrastructure Obstruction List - Signage

Revision: 01

Completed by: Alexander Beeston

Date: May 9, 2017

Purpose:

The following list details the Municipal Infrastructre that will be damaged, destroyed or otherwise adversely affected by the delivery of wind turbine rotor blades during the Amherst Island Project. A comprehensive map detailing the locations of each obstruction can be found in Appendix A.

Obs #	Location of Obstruction	Description of Obstruction	Picture:
1	Northeast corner of the intersection of Second	The road sign will potentially obstruct the swing radius of a rotor blade being delivered. Sign will be removed for temporary overbuild, to be re-installed once project is complete.	The state of the s
2	South side of South Shore Rd. Latitude: 44.150704 Longitude: -76.662459	The road sign will obstruct the swing radius of a rotor blade being delivered if determined to be greater than five feet above the road surface. This sign will be re-instated after completion of each delivery.	05 05 2017

Obs	Location of	Description of Obstruction	Picture:
#	Obstruction	•	i icture.
3	North side of South Shore Rd. Latitude: 44.150729 Longitude: -76.662610	The road signs on the north side of the road will potentially obstruct the swing radius of a rotor blade being delivered if determined to be greater than five feet above the road surface. This sign will be re-instated after completion of each delivery.	No. 37 (10) To
4	South side of South Shore Rd. Latitude: 44.150684 Longitude: -76.662530	The road sign will potentially obstruct the swing radius of a rotor blade being delivered if determined to be greater than five feet above the road surface. This sign will be re-instated after completion of each delivery.	05.05.2017
5	South side of South Shore Rd. Latitude: 44.151196 Longitude: -76.662307	The three turn markers pictured will potentially obstruct the swing radius of a rotor blade being delivered if determined to be greater than five feet above the road surface. This sign will be re-instated after completion of each delivery.	93. 33 <u>2</u> 7/9
6	North side of South Shore Rd. Latitude: 44.151217 Longitude: -76.662383	The road sign will potentially obstruct the swing radius of a rotor blade being delivered. This sign will be re-instated after completion of each delivery.	

Obs	Location of	Description of Obstruction	Picture:
#	Obstruction	Description of Obstruction	ricture:
7	South side of South Shore Rd. Latitude: 44.153351 Longitude: -76.660101	The road sign will potentially obstruct the swing radius of a rotor blade being delivered. This sign will be re-instated after completion of each delivery.	05 05 3017
8	North side of South Shore Rd. Latitude: 44.160934 Longitude: -76.652299	The object marker will potentially obstruct the swing radius of a rotor blade being delivered. This sign will be re-instated after completion of each delivery.	58 50 7
9	North side of South Shore Rd. Latitude: 44.163283 Longitude: -76.648232	The mail box and sign will potentially obstruct the swing radius of a rotor blade being delivered. This sign will be reinstated after completion of each delivery.	55 65 2017
10	South side of South Shore Rd. Latitude: 44.171261 Longitude: -76.630217	The object marker will potentially obstruct the swing radius of a rotor blade being delivered. This sign will be re-instated after completion of each delivery.	95 .95 2011

